

Using Multiple Setups

I-DEAS® Tutorials: Milling Projects and Turning Projects

In this tutorial, you'll machine the bracket shown above. using a 3-axis machine. Because the machine can't rotate about the 4th and 5th axes, you can't reach all the surfaces in one setup. You'll create multiple setups and reposition the workpiece so the surfaces to be machined are aligned with the positive Z axis, or the cutting direction of the tool.

Learn how to:

- orient the part to the default MCS
- create new setups

Before you begin...

Prerequisite tutorials:

- all tutorials under the Modeling Fundamentals menu
- Introduction to Generative Machining
- Building a Setup Assembly
- Generating In-process Stock and Checking Validity
- Working with Tools and Tool Catalogs
- Picking Holes
- Setting Machining Parameters for Hole-making Operations

The file you need for this tutorial is distributed with the product. You must copy it into your local directory.

Move to the local directory where you want to copy the file. Then:

In UNIX:


```
cp $SDRC_INSTL/examples/nc/  
tut_multiple_setup.arc .
```

In Windows:

```
copy %SDRC_INSTL%\examples\nc\  
tut_multiple_setup.arc .
```

If you can't copy the file, you may have to set up the variable needed to copy from the I-DEAS installation.

```
. sdrc_oadev
```

 If you can't access the file, contact your system administrator. The file may not be installed.

If you didn't start I-DEAS with a new (empty) model file, open a new one and give it a unique name.



File

Open

Open Model File form



Model File name: any unique name



OK

Make sure you're in the following application and task:




Application: Manufacturing



Task: Generative Machining

Set your units to inches.




Options

Units




Inch (pound f)


Import the archive file that contains the parts and tools that you need to complete this tutorial. Importing an archive file can take several minutes. Be patient.



Import Selections form



File Name Input form



The Manufacturing application quits, an informational message is displayed (the message will dismiss automatically), and the archive file is imported.

Import Archive File Status




Be sure to check the List region to be sure that the parts imported properly.



A second informational message is displayed (the message will dismiss automatically) and the Manufacturing application starts.

Create a job.



NC Job Create form

Job Name: Setup Machine Bracket



OK

Add the part to the job.



Get



From Bin/Library


Select Part/Assembly form



tut_bracket



OK



Recovery Point

 *File*
Save

Warning!

If you're prompted by I-DEAS to save your model file, respond:

 *No*

Save only when the tutorial instructions tell you to—not when I-DEAS prompts for a save.


If you make a mistake at any time between saves and cannot recover, reopen your model file to the last save and start over from that point.

Hint

To reopen your model file to the previous save, press Control-Z.

In the next steps, you'll align the surface to be machined in relation to the Z axis of the global-space coordinate system. The global-space coordinate system is the default origin and orientation of the machine tool without a 4th or 5th axis. You can use it to represent a 2-, 2 1/2-, or 3-axis machine tool.

You'll then create a volume clear operation and generate a toolpath.




What: Display the global-space coordinate system. The part is located at the global-space coordinate system, which acts as the default origin.

How:




Workplane Attributes form


- ☒ *Display Origin—On*
- ☐ *OK*




What: Rotate the part about the X axis so the surface to be machined aligns with the Z axis. The Z axis represents the axis of rotation for the tool spindle.


How:




 (twice)

 **Check I-DEAS Prompt.**

Enter rotation angles: -90, 0, 0



Result



Things to notice


The side of the part is aligned with the Z axis.

Recovery Point



What: Create a volume clear operation.

How:



NC Job Planning form



OpGroup-1



OpGroup Specification form



Operation Selection form




Category: Milling



Type: Volume Clear



Create

 Don't close the Operation Specification form.

What: Name the operation and pick the surface to be machined.


How: _____

Operation Specification form

Name: Mill Face A



1



 Continue on the next page to define the stock.

What: Define the stock as a footprint. To learn more about defining stock for volume clear operations, complete the Creating Face Mill and Volume Clear Operations tutorial.

How:

Stock Specification form



System Defined Stock: On




Set Stock Area To: Convex Foot Print



With XY Offset of: 0.5



Stock Top



Check I-DEAS Prompt.

Accept the surface, if necessary.



Stock Top: 1.9

The top of the part is located at 1.81102. You enter 1.9 to specify material to machine above this surface.



Don't close the Stock Specification form.


What: Define the bottom of the stock.

How:

Stock Specification form




Stock Bottom



Accept the surface, if necessary.



OK

 Don't close the Operation Specification form.

What: Use a 2" diameter end mill to machine the surface.

How:


Operation Specification form



Cutting Tool Specification – Mill form




Item Selection form



Cutting Tool Specification—Mill form



 Don't close the Operation Specification form.

What: Specify the cut pattern as *Zig Zag with Stepper out of Workpiece*. Then set the cutting passes as .5" beyond the boundary of the stock. This ensures that material is removed from the edges of the part.

Set the *Default Finish Allowance* to zero so no material is left on the surface.

How:

Operation Specification form



Machining Parameters—Cut form



Cut Pattern



Cut...

Allowances and Tolerances...



Default Finish: 0



OK




Don't close the Operation Specification form.

What: Generate the toolpath.

How:

Operation Specification form



Things to notice


The toolpath extends past the edge of the part by .5". Also, the tool follows a zig-zag cut pattern. It doesn't stay in contact with the part throughout the entire toolpath because you accepted the default cut type of *Climb*.

Recovery Point




In the next steps, you'll create two setups. For each setup, you'll rotate the part to align the surface to be machined with the Z axis of the global-space coordinate system. You'll then create an operation to machine the surface.

In general, if you must modify a setup assembly, such as moving the part or changing a clamp, for a new machining operation, you should create a new setup. Changes to the parts in a setup assembly invalidate any operations in the current setup. When you create a setup, the software copies the setup assembly from the previous setup so you can modify it.



What: Create a setup.

How:



NC Job Planning form



Deselect *Mill Face A* by pressing the Control key and selecting *Mill Face A*.



Setup Specification form






Dismiss



Dismiss

What: Rotate the part 180 degrees about the Y axis to machine the other side of the part.

How:




👁👁 *Check I-DEAS Prompt.*

Enter rotation angles: 0, 180, 0



Result



Things to notice

The side of the part is aligned with the Z axis.

Recovery Point



What: Modify OpGroup-2 and create a volume clear operation.

How:



NC Job Planning form



Opgroup-2

OpGroup Specification form



Operation Selection form




Category: Milling



Type: Volume Clear





Create

 Don't close the Operation Specification form.

What: Name the operation and select the surface to be machined.


How:

Operation Specification form



Stock Specification form



 Don't close the Operation Specification form.

What: Get a 2" diameter end mill from the tool catalog.

How:

Operation Specification form



Cutting Tool Specification – Mill form



Item Selection form



2" dia end mill



OK

Cutting Tool Specification—Mill form



OK




Don't close the Operation Specification form.

What: Generate a toolpath.

How:


Operation Specification form



Things to notice


The machining parameters from the previous operation are applied to this operation.

Recovery Point



What: Create a final setup.

How:






Setup Specification form

 *Dismiss*

What: Rotate the part -90 degrees about the Y axis.

How:



(twice)




Check I-DEAS Prompt.

Enter rotation angles: 0, -90, 0



Result




Things to notice

The front of the part is aligned with the Z axis.

What: Create a copy mill operation.

How:



NC Job Planning form



Opgroup-3

OpGroup Specification form



Operation Selection form




Category: Milling



Type: Copy Mill



Create


 Don't close the Operation Specification form.

What: Name the operation and select the surface to be machined.

How:

Operation Specification form


Name: Mill Face C



Surface Selection form



Dismiss

 Don't close the Operation Specification form.

What: Get a 1/2" diameter end mill for the operation.

How:

Operation Specification form



Cutting Tool Specification – Mill form




Item Selection form



1/2" dia end mill



 Don't close the Operation Specification form.

What: Create the toolpath.

How:


Operation Specification form



I-DEAS Warning



Dismiss



Things to notice

For this toolpath, the tool retracts only after the side of the hole has been machined. It then makes one rapid move and engages on the other side.

Recovery Point



Tutorial wrap-up

You've completed the Using Multiple Setups tutorial.